

IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 200209125-1

IN RE APPLICATION OF: U.S. Patent No. 6,917,232

USPTO CONFIRMATION CODE: 8215

APPLICATION NO.: 10/733,790

FILED: Dec. 10, 2003

EXAMINER: Tuan T. Lam

GROUP ART UNIT: 2816

FOR: METHOD AND APPARATUS FOR GENERATING A QUADRATURE CLOCK

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/733,790, now Patent Number 6,917,232.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

☒ All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to Deposit Account No. 082025.



☐ All errors were the fault of the applicant and, accordingly, please charge **\$100.00** to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

☐ The errors were the fault of both the applicant and USPTO and, accordingly, please charge **\$100.00** to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

On the face page, in field (57), under "Abstract", in column 2, line 1,
delete "dock" and insert -- clock --, therefor.
(Abstract filed on Dec. 10, 2003, page 16, line 2)

On sheet 3 of 8, Fig. 3, delete



--, therefor.

(Amendment to drawings filed on Apr. 04, 2005, sheet 3/8, Fig. 3)

In column 1, line 43, before "are" delete "dock" and insert -- clock --, therefor.
(Specification filed on Dec. 10, 2003, page 1, line 31)

In column 1, line 43, after "quadrature" delete "dock" and insert - - clock - -, therefor.

(Specification filed on Dec. 10, 2003, page 1, line 32)

In column 4, line 47, delete "390A-CLK2" and insert - - 390A=CLK2 - -, therefor.

(Specification filed on Dec. 10, 2003, page 7, line 1)

In column 6, line 19, delete "dock" and insert - - clock - -, therefor.

(Specification filed on Dec. 10, 2003, page 9, line 20)

In column 6, line 38, delete "dock" and insert - - clock - -, therefor.

(Specification filed on Dec. 10, 2003, page 10, line 2)

In column 6, line 49, delete "docked" and insert - - clocked - -, therefor.

(Specification filed on Dec. 10, 2003, page 10, line 11)

In column 7, line 52, in Claim 8, delete "dock" and insert - - clock - -, therefor.

(Claims filed on Dec. 10, 2003, page 13, in Claim 8, line 1)


In column 8, line 26, in Claim 13, delete "dock" and insert - - clock - -, therefor.

(Claims filed on Dec. 10, 2003, page 14, in Claim 13, line 5)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

6/19/09
DATE



Name: Steven L. Webb
Registration No.: 44,395

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY
Intellectual Property Administration
P.O. Box 272400
Fort Collins, Colorado 80527-2400

PATENT NO. : 6,917,232

APPLICATION NO. : 10/733,790

ISSUE DATE : Jul. 12, 2005

INVENTOR(S) : Perry M. Wyatt, et al.

Figure 1 is a block diagram of a PLL system with two PLLs. The first PLL (left) includes a REFCLK input, a PHASE LOCKED LOOP 310, a DIVIDER (÷2), and a 2XCLK 316 output. The second PLL (right) includes an S_DIFF CONVERTER 320, a DIST BLOCK, a DIFF_S CONVERTER 332, a DIFF_S CONVERTER 330, and two D FLIP FLOPS (350B, 360B) with outputs CLK1 380B and CLK2 390B. A dashed line separates the two PLLs.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 3 of 3

PATENT NO. : 6,917,232
APPLICATION NO. : 10/733,790
ISSUE DATE : Jul. 12, 2005
INVENTOR(S) : Perry M. Wyatt, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 1, line 43, before "are" delete "dock" and insert - - clock - -, therefor.

In column 1, line 43, after "quadrature" delete "dock" and insert - - clock - -, therefor.

In column 4, line 47, delete "390A-CLK2" and insert - - 390A=CLK2 - -, therefor.

In column 6, line 19, delete "dock" and insert - - clock - -, therefor.

In column 6, line 38, delete "dock" and insert - - clock - -, therefor.

In column 6, line 49, delete "docked" and insert - - clocked - -, therefor.

In column 7, line 52, in Claim 8, delete "dock" and insert - - clock - -, therefor.

In column 8, line 26, in Claim 13, delete "dock" and insert - - clock - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY
Intellectual Property Administration
P. O. Box 272400
Fort Collins, Colorado 80527-2400

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.